
NOTE: Do not adjust Pivot Bolt



A ENSURE FIREARM IS UNLOADED




- Remove EOTech™ G33 Magnifier from factory mount and set it aside.
- Up-end and seat G33 Magnifier in FAST mount arm (do not use shim from 0EM magnifier kit). Insert included screws. Tighten screws to finger tight, then another 1/8 1/4 turn. DO NOT EXCEED 30 IN-LBS.





A ENSURE FIREARM IS UNLOADED



- 3 FAST Magnifier Mounts use a Force-to-Overcome mechanism.
- Grasp magnifier body and pivot assembly down to stow position. Repeat in reverse to bring magnifier back into active position.